



Proposed Miami Bridge Improvements

We Have To Do Something!

K0999 08-08-07
Sway bracing w/ pk rust & sect loss @
btm corners N end span 3 from S



K0999 06-14-05
Small hole in E OS strgr @ L-16'



K0999 06-15-05
Flat plt brgs shifted 1" N @ bt 11



K0999 06-15-05
SIP forms rusted thru @ bt 8



K0999 06-15-05
13" x 2" hole in web
of 7th flr bm N of pier 7 E side



K0999 08-08-07
os ends of flbs w/ hvy pk rust &
sect loss span 3

